Detailed Building Survey / Homebuyers Report

A Brief Guide

Jaggard MacLand offer two types of survey, a Detailed Building Survey and a HomeBuyer Report.

Previously known as a Full Structural Survey, a Detailed Building Survey is a wide-ranging inspection of a property. It is the most comprehensive of the surveys available for residential properties and will provide a detailed evaluation of a property's condition.

The Detailed Building Survey report will describe the condition of each element of the house and identify the property's defects, their apparent cause, the urgency of repair, maintenance options and may also include an indication of the cost to repair.

Although this survey is more expensive, a Detailed Building Survey is a comprehensive and detailed evaluation of a property's condition and construction.

A Detailed Building Survey is generally recommended for properties that have the following characteristics:

- Are older and built more than 100 years ago
- Have undergone major extension or alteration
- Are larger and offer extensive accommodation
- You plan to alter in the future
- Are of non-traditional construction



The HomeBuyer Report is the most frequently undertaken survey which provides a report of the condition of the property and will give you professional advice to allow you to make an informed decision of whether to proceed. A comment on value can be provided if required.

The report is produced in a template provided by the RICs and provides a description alongside a condition grading. This numeric grading provides a quick guide as to the general condition of the property.

A HomeBuyer Report is generally recommended for properties with the following characteristics:

- Were built within the last 100 years
- Are of conventional construction
- Are in a reasonable condition, as far as you can tell and have not been significantly altered

Please contact Philip Pearcey or Greg Rowland for more information on our range of surveys:

- Full Building Survey
- Homebuyers Survey
- Snagging Survey
- Commercial Property Survey

Please contact:

Greg Rowland MRICS (E) gjr@jaggardmacland.co.uk (T) 01494 689616 (M) 07843 054770

Phil Pearcey MRICS (E) <u>pep@jaggardmacland.co.uk</u> (T) 01494 689615 (M) 07729 623979

Jaggard Macland LLP McBride House 32 Penn Road Beaconsfield Bucks HP9 2FY





Jaggard Macland

Professional Property Services



Landlord Property Services	Tenant Property Services	Residential Property Services	
Property Management Graham Atkinson	Search & Relocation Simon Harper	Residential Building Survey Phil Pearcey	
Rent Review & Lease Renewal Steven Macdermott	Rent Review Negotiation Simon Harper	New Home Snagging Phil Pearcey	
Property Investment	Lease Expiry Negotiation	Residential Property Investment	
Steven Macdermott	Simon Harper	Greg Rowland	
Sale & Letting of Commercial Property Steven Macdermott	Lease Restructuring & Variation Simon Harper	Residential Lease Extension Greg Rowland	
Commercial Valuation Steven Macdermott	Building Survey Phil Pearcey	Block Management Greg Rowland	
Project Management	Portfolio Management	Residential Property	
Phil Pearcey	Simon Harper	Management Greg Rowland	
Commercial Building Survey Phil Pearcey	Tenant Dilapidations Steven Macdermott	Residential Valuation Greg Rowland	
Landlord Dilapidations Steven Macdermott	Schedule of Condition Phil Pearcey		

		Partners	
Graham Atkinson	(T) 01494 689603	(M) 07802 765662	(E) gra@jaggardmacland.co.uk
Simon Harper	(T) 01494 689614	(M) 07801 109649	(E) srh@jaggardmacland.co.uk
Steven Macdermott	(T) 01494 689619	(M) 07764 476931	(E) srm@jaggardmacland.co.uk
Greg Rowland	(T) 01494 689616	(M) 07843 054770	(E) gjr@jaggardmacland.co.uk



